

State of Utah

Department of Natural Resources

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA Division Director JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

Representatives Present During the Inspection:						
Company	Dennis Oakley Environmental Engineer					
OGM	Steve Demczak Environmental Scientist III					

Inspection Report

Permit Number:	C0150017			
Inspection Type:	PARTIAL			
Inspection Date:	Tuesday, January 15, 2008			
Start Date/Time:	1/15/2008 10:00:00 AM			
End Date/Time:	1/15/2008 1:00:00 PM			
Last Inspection:	Monday, December 08, 2008			

Inspector: Steve Demczak, Environmental Scientist III

Weather: <u>Cold, 20's, Snow Covered</u> InspectionID Report Number: <u>1892</u>

Accepted by: jhelfric

2/23/2009

Permitee: PACIFICORP

Operator: ENERGY WEST MINING CO

Site: **DES BEE DOVE MINE**

Address: PO BOX 310, HUNTINGTON UT 84528

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: RECLAIMED

Mineral Ownership

Types of Operations

✓ Underground☐ Surface

Reprocessing

134.31	Total Permitted			
36.02	Total Disturbed			
	Phase I			
	Phase II			
1,000	Phase III			

Current Acreages

✓ Federal☐ State

☐ County

☐ Other

Loadout
Processing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

No violations have been issued.

Inspector's Signature:

Steve Demczak, Environmental Scientist III

Date

Monday, January 21, 2008

Inspector ID Number: 39

Permit Number: C0150017 Inspection Type: PARTIAL

Inspection Date: Tuesday, January 15, 2008

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	✓		✓	
3.	Topsoil	✓		•	
4.a	Hydrologic Balance: Diversions	✓		~	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments		✓		
4.c	Hydrologic Balance: Other Sediment Control Measures	✓		✓	
4.d	Hydrologic Balance: Water Monitoring		✓		
4.e	Hydrologic Balance: Effluent Limitations		✓		
5.	Explosives		✓		
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments		✓		
8.	Noncoal Waste	V		✓	
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading	✓		✓	
13.	Revegetation	✓		✓	
14.	Subsidence Control		✓		
15.	Cessation of Operations				
16.8	a Roads: Construction, Maintenance, Surfacing		✓		
16.k	Roads: Drainage Controls		✓		
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0150017 Inspection Type: PARTIAL

Inspection Date: Tuesday, January 15, 2008

Page 3 of 3

2. Signs and Markers

The identification signs is located on the cattle trail to the mine site.

3. Topsoil

All topsoil was used in reclamation.

4.a Hydrologic Balance: Diversions

There were no signs of erosion to the diversion. The diversions would function during a storm event.

4.c Hydrologic Balance: Other Sediment Control Measures

The mine site is pocked for sediment control.

8. Noncoal Waste

The site was clear of non-coal waste materials.

12. Backfilling And Grading

The mine site is backfilled and graded.

13. Revegetation

Vegetation is snow covered.